

FIG. 1 PRIOR ART




FIG. 1 PRIOR ART

EXCHANGE 6

SG 31

MGC 8

MGC 9




FIG. 2 PRIOR ART

10067226-00000
200000-000000




FIG. 3 PRIOR ART

10057296-000000




FIG. 4




FIG. 5

2

MGC	MGC FAULT INFORMATION	LINE CLOSE INFORMATION
#1	0	0
#2	1	0
#3	1	1
#4	0	0
.	.	.
.	.	.
.	.	.

FIG. 6




FIG. 7




FIG. 8

LINE CLOSE OPERATION




FIG. 9

LINE CLOSE CANCEL OPERATION




FIG. 10

FIG. 11




FIG. 11




FIG. 12